

# Locomotive 3463 Move Preparation Report



About the Coalition for Sustainable Rail	
the Coalition for Sustainable Rail (CSR) is dedicated to the refinement of solid biofuel technologies for use it orld's first carbon-neutral higher speed locomotive. Our team is a combination of the University of Minney and Sustainable Rail International (SRI), a 501c(3) nonprofit dedicated to the research and development of modern steam locomotives. A scientific and educational organization, CSR's mission is to advance biofuel rail production; to research and develop sustainable railroad locomotives; to promulgate associated sustainable rail and informational activities to increase wareness of sustainable railroad locomotives.	esota esearch able

Cover Photo - CSR Technical Advisor Ing. Wolf Fengler walks in front of 3463's 84" driving wheels on a late night work session. The locomotive's main

©2013. This paper is covered by the Creative Commons "Attribution-No Derivs-NonCommercial" license (see http://creativecommons.org). It may be reproduced in its entirety as long as the Coalition for Sustainable Rail is credited, a link to CSR's website is provided and no charge is imposed. The paper

rods have been removed and placed on the running boards in this photo and all axle roller bearings have been inspected and cleaned.

may not be reproduced in part or in altered form, or if a fee is charged. Please let CSR know if this paper reprinted (see www.csrail.org).



### Introduction:

The Coalition for Sustainable Rail (CSR) sent a work crew to Topeka, Kansas in June 2013 to prepare its steam locomotive number 3463 for its first substantial move in 57 years. The locomotive was placed in the park with a dedication ceremony on November 3, 1956. It sat parallel to Topeka Avenue until the mid 1980's when, as the Kansas Expocentre was being constructed, the locomotive was moved roughly 500 feet downhill and away from the main road.

As CSR prepares to move the locomotive out of the park, it is critical to ensure that when the locomotive rolls, it does not damage itself. Because there has been little-to-no maintenance to core engine components since it was placed in the park, including no work to roller bearing axles and side rods, CSR needed to perform a detailed inspection and re-lubrication of those core components. To accomplish that, CSR: 1) drained, inspected and refilled all of the roller bearings on the locomotive's axles; 2) pulled off the main side rods and prepared the remaining rods to be cleaned and greased just-prior to the locomotive's move and 3) disconnected the main rods from each crosshead, placing them on each respective running board, thereby isolating the piston from reciprocal movement during the upcoming move.

This document provides written and illustrated detail of work performed by the CSR's expert, volunteer crew. All materials were provided through tax-deductible donations made by its many donors.

Readers that find themselves intrigued by the content of this document and the work of CSR are invited to consider making a tax-deductible donation in support of its efforts! You may do so at **www.csrail.org/support** 

## Axle Bearings:

Like many mainline steam locomotives manufactured after 1930, locomotive 3463 was designed and manufactured with low-resistance roller bearings on each of its axles. Designed by A.T.&S.F. and Baldwin Locomotive Works mechanical engineering staff, the 3460 class of locomotives were some of the most powerful and modern high-speed passenger steam locomotives of their type ever designed. Unlike most other roller bearing-equipped steam locomotives of the era which featured Timken Brand "Tapered Roller Bearings," the designers decided to equip all 3460 class locomotives with SKF Brand "Spherical Roller Bearings" on all lead, main, trailing and tender axles (26 bearings in total).

Invented by Swedish company SKF, the spherical roller bearing has many similar attributes to those of the tapered roller bearing, but features greater resilience in the face of misalignment and flexing of axles under stress. According to the company: Spherical roller bearings have two rows of rollers, a common sphered






Fig. 8.311—Engine truck journal assembly of SKF spherical journal bearings.



**Bearing Box Design:** Taken from the 1941 locomotive cyclopedia, this drawing shows cross sections through SKF lead and trailing truck axles boxes, as used on locomotive 3463.



**Where a roller meets the sphere:** This skewed view of the SKF-designed spherical roller bearing illustrates its cross section quite clearly.

outer ring raceway and two inner ring raceways inclined at an angle to the bearing axis. The bearings are selfaligning and insensitive to misalignment of the shaft relative to the housing, which can be caused, for example, by shaft deflection. Spherical roller bearings are designed to accommodate heavy radial loads, as well as heavy axial loads in both directions.


CSR contacted SKF regarding the bearings on its locomotive, including inspection protocol and lubrication standards prior to performing work on the engine. SKF indicated that the roller bearings should be drained completely, inspected visually via boroscope and refilled with appropriate, yellow-metal-safe lubricant.

Beginning with easy-to-access trailing truck bearings, CSR began draining the half-century old bearing oil, which flowed out of the drain plug with little difficulty. Once flow waned to a trickle, the CSR crew unbolted the cast bearing covers and removed them. Unsure what to expect, CSR discovered bearings in shockingly good condition considering the total lack of maintenance. Seeing no visible pitting on any of the bearings and little contaminant in the oil, the CSR crew went about draining the remainder of the axles of their oil.

Draining lead truck and main axle bearing oil proved an acrobatic exercise. Despite having 84" driving wheels and bearing box centers half-as-high, the design of the locomotive's brake rigging made accessing the drain plugs without an inspection pit an exercise in

contortionism. Working in pairs of two, one CSR crew member would clip all safety wires on the plugs, allowing them to rotate freely, while another member would lug along a drain pan, 15" wrench, rags and mats to begin the process of draining between three and seven quarts of oil from each of the bearing boxes, dependent upon the bearing box design. Again, as draining and inspection continued, CSR was pleased at the condition of each of the bearings.

Once all bearings had been drained, CSR began the process of refilling each with fresh oil. The lead and trailing truck bearings could be easily filled with a standard funnel and pitcher, but the driving axle boxes, which had traditionally been filled via oil pump, could not be easily replenished with bucket and funnel. As an improvisation, CSR attached 10 feet of flexible tubing to the end of the funnel, snaking one end between driving wheel center openings and the frame and into the fill plug opening while pouring oil into the funnel from the outside of the locomotive.



Shine with a paper seal: When crews opened the trailing truck axle boxes, they were surprised with clean, rust-free bearings.



**Kansas in Summer:** With sun beaming down, crew members discuss next steps with the side rods following removal of the eccentric crank.

## Rod Bearings:

The power of a steam locomotive is transmitted from pistons to a series of side rods that connect the driving wheels. In 3463's case, each of two pistons theoretically generates up-to 130,120 lbs of force, the effective force is often much lower due to internal inefficiencies in the steam circuit common to the 3460 class, something CSR will address in its rebuild. A main rod connects the piston rod to the main driving pin, and coupling rods transmit that driving force to the remaining driving wheels. The combination of driving wheel diameter, piston stroke and diameter, boiler pressure and weight on drivers all factor into the steam locomotive's pulling power, known as "tractive effort."

To prevent damage to the piston and cylinder lining during its upcoming move, CSR needed to disconnect the piston rod from the main rod on each side of the locomotive, and to remove the latter prior to shipment to Minneapolis. This work entailed removing the union link, driving out the wrist pin, removing the eccentric rod and crank and positioning the crosshead in such a manner that the main rod could be removed without torsion about its brass bearing.

The first (and easiest) step was removal of the union links¹ from the wrist pins.² CSR was then able to access the wrist pin<sup>2</sup> itself. Designed to transmit the full force of each piston, the wrist pins<sup>2</sup> are tapered and keyed, meaning they will not rotate or loosen during highspeed operation. Using a custom-made tool to protect the threads on the pin, CSR employed a persuasive 10 lb sledge hammer to loosen the wrist pins.<sup>2</sup> Once the pins began to move, CSR used blocking and nylon straps to prevent the rods from binding on the wrist pins.

The crew then turned its attention to the eccentric rods<sup>3</sup> (another easy-to-remove item) and the eccentric cranks<sup>4</sup> (not-so-easy-to-remove). With eccentric rods<sup>3</sup> removed, CSR needed to remove two, 18"-long tapered




**Custom Wrenches:** Measured, cut and machined on-site, the 10.5" diameter nuts required one-off wrenches, one of which is rough-fit above.

pins, spread the end of the eccentric crank<sup>4</sup> with a wedge and carefully coerce the crank off of the end of the main axle. The eccentric crank<sup>4</sup> has one tapered pin that is aligned directly through the center of the main crank pin and one pin just offset, proving cinching force through the forks of the crank.

With large wrenches and persuasion of that sledge hammer, the crew had the eccentric cranks4 removed in little time, revealing rod brasses on the locomotive that were in outstanding condition.

Folk lore always seems to indicate that the locomotive given to such-and-such city was rebuilt just-prior to





**R3463 AQ 2 20 53:** Punched into fresh bearings 60 years ago, those numbers indicate a set of running gear brasses fresh out of the shop. Unlike many other locomotives, 3463 features segmented brasses which feature three seams (most evident match 1:1) to accomodate expansion with heat.

being stuck into whatever park it currently sits. Though often apocryphal, in the case of 3463, it appears that is almost the case. The A.T.&S.F. maintained inspection tags and stamped parts installed on each of its steam locomotives when work was performed to maintain a detailed record of work undertaken. The nearnew rod bearings exposed when crews removed the eccentric crank read: AQ 2 20 53. This is code for work performed at the Albuquerque, New Mexico shop, with brasses installed on February 20, 1953. Considering the locomotive was taken out of service in 1954 and the visual inspection of the bearings, it appears the engine has a lot of life left in it!

Once both eccentric cranks<sup>4</sup> were removed, CSR then had to move the locomotive for the first time in 24 years to align holes in the number one driving wheel with the back side of each wrist pin<sup>2</sup> for removal. The length of the pin is longer than the distance between the back of the crosshead and the driving wheel, meaning an opening in the wheel center has to be lined up with the wrist pin<sup>2</sup> opening to allow it to be removed.

With a 20 ton jack and a bit of leverage, locomotive 3463 lurched forward with ease, rolling on newly-

lubricated roller bearings. Crews moved the engine backwards and forwards, lining up the wristpins<sup>2</sup> with the correct wheel opening and driving each pin the remainder of the way into the hands of waiting workers.

The main rods<sup>5</sup> still blocked and securely chained, the crossheads<sup>6</sup> needed to be pushed far enough forward to allow the rod to rotate freely and, subsequently, be removed. Using pry bars and jacks, the CSR crew moved each crosshead<sup>6</sup> to clearance, freeing the main rod to drop. Once the steel safety straps were unbolted, CSR used a large forklift and straps to support the weight of the rod, removed chains and blocking, slid the rod off of each pin and hoisted them up onto the running boards.

When all brasses had been removed and stored, the revealed crank pins appeared to be in very good condition. The alemite grease applied 57 years ago by the Santa Fe had not worn off, protecting the pins and preventing excessive corrosion.

Once the main rods were placed on the running boards, the engine and tender were separated. Of interest, the six-axle, 174,000 lb tender rolled with a simple push of two people; a tribute to the bearing construction.



Working into the night: Illuminated by work lamps, the figure of 3463 is nothing short of imposing. The main rods have already been removed, brasses stored, eccentric cranks replaced and locomotive rolled back-and-forth by the time this image was taken.

# **Next Steps:**

Knowing the locomotive can roll freely without damage and that the bearings are in top condition is the first step to removing the steam engine from the park and returning it to the rails.

Now comes the logistical acrobatics.

CSR is working with a group consisting of expert heavy equipment operators, industry partners, sponsors and local municipalities to finalize the extraction of locomotive 3463. Even empty, the locomotive still consists of two, 50-foot-long pieces weighing in excess of 575,000 lbs combined.

However, an experienced team with proper equipment will have little difficulty moving the massive machine out of the park, returning to the rails for shipment to Minnesota and its remanufacture. Keep an eye on the CSR website or sign up for its email newsletter to stay informed.

While this planning progresses, CSR continues to line up donations and participation from new Supporters and Industry Sponsors. An associate member of the American Boiler Manufacturers Association, CSR has begun to involve that network of professionals and industry leaders, many of whom are interested in working with, supporting and innovating with CSR's locomotive boiler experts.

If you have yet to do so, please consider making a tax-deductible donation in support of the Coalition for Sustainable Rail. The advanced biofuel, modern steam locomotive and advanced electricity generation technologies it champions are certain to have an impact on a prosperous future, and it is only through your support that it can hope to achieve success.

Find out more: www.csrail.org/support

**Email List** | Join our email list at the top of any of our web pages: www.csrail.org/email

Facebook | www.facebook.com/csrail

Mail | Coalition for Sustainable Rail | P.O. Box 120361 | New Brighton, MN 55112

